EPI PA REVIEW ROUTE SLIP

ROUTING AND TRANSMITTAL SLIP

		symbol, roo ency/Post)	m numb	oer.	W =	2 (Initials	Date
ı. ⊂Se	ction	Chief	/V 2.	ياد ا −rev	iew			
2. Ch	ief	H-4-4	3-()	-rev	iew			
3. – PI	RC			-log	-i n			
i Sc	hwin	1 H-4-4		арр	rove	_		
PF				-loq	in Fina	1	<u> </u>	
s. Sm	ith I	1-4-4		-copy	&distr.	ibute		
Action			File	-retu	m orig	in auto	ato Fatu	aff
Approv	/ai		For C	Clearance		Per	Conversat	ion
As Red	As Requested For Correction Prep			repare Reply				
Circuit	Circulate For Your Information See			Me				
Comm	Comment Investigate Signature		ature					
Coord	ination		Justi	ify				
REMARK	S							

		/	1
Poviou	For	(ZNB	Inc

h	•	c)	-	T	P	
11	6			_		3

High Priority

(h) Order Candidate

Imminent & Substantial · Contract Perfor-Endangerment

Attached

- PA Review Form
- NCAPS Sheets
- Stabilization Checklist
- mance Form
- RCRIS Entry Form

DO NOT use this form as a RECORD of approvals, concurrences, disposals clearances and similar actions

	Cidarancas, and aminar actions	
FROM: (Name, org. s)	rmbol, Agency/Post)	Room No.—Bldg.
	/ 0 0 $- 0$	\$ 10160
Trank	(9av/Viv (17-3-1)	Phone No.
		0,0,7
5041-102	OPTION	AL FORM 41 (Rev. 7-76)



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

75 Hawthorne Street San Francisco, CA 94105

<< ENFORCEMENT CONFIDENTIAL>>

MEMORANDUM

DATE:

December 6, 1994

SUBJECT:

RFA Review

Facility:

GNB Inc. (formerly Gould Ine)

FROM:

Frank Gardner

TO:

Larry Bowerman, Chief

Corrective Action Section

I. FACILITY DESCRIPTION

Facility Name:

GNB Inc. Los Angeles Smelter (formerly Gould Inc.)

RFA/date: 10/31/90

Address:

2700 South Indiana Street

Los Angeles (Vernon), CA 90023

Los Angeles County

EPA ID Number:

CAD 097 854 541

DTSC Region:

3

RWQCB Region:

4, Los Angeles

A. Brief Description of Facility Operations and Hazardous Waste Management:

GNB is a secondary lead smelter that buys lead-bearing wastes (mostly spent automotive batteries) and scrap lead from other facilities and smelts them onsite into new lead ingots. The 24 acre site is located in an industrial area of Vernon, California. Prior to 1922, a meat rendering plant was located on the site. Morris Kirk and Sons smelted lead on site from 1922 to 1979 (Morris Kirk and Sons became a division of NL industries in 1973). Gould Inc. bought the site and continued operations from 1979 to 1984. GNB bought the facility in 1984 and continues to operate it at present. Lead smelting operations began at this site in

1922 in the southeast corner of the site, gradually expanding over the next 60 years to cover most of the site. The facility was reconstructed in 1982 by Gould Inc.

Lead-acid batteries received at GNB for recycling are stored, cracked, drained, washed, and separated into their component materials, namely lead, plastic, and rubber. Lead is smelted onsite, and the rubber is used to fuel the smelting furnaces. The plastic chips are trucked to KW plastics in Bakersfield for plastic recycling (a sometimes sloppy process that has resulted in STLC-hazardous lead-containing wastewater dripping from the trucks onto Interstate 5).

The main process units included in the onsite lead smelting operations include battery receiving buildings, raw material preparation system, battery crushers, reverbatory furnace, blast furnace, and baghouses. During the RFA, a total of 38 SWMUs and 2 AOCs were documented. Of the 38 SWMUs, 11 have had documented releases, namely SWMUs 3,6,9,10,11,12,14,15,24,28,&29. According to RCRIS, at least six of the SWMUs at this site are RCRA-regulated units.

B. SWMU Release Inventory:

The following is a table of Solid Waste Management Units (SWMUs) releases and release potential to the various media. Releases are described with either a "D" for Documented, a "V" for Visual, or a "P" for Potential. Potential releases are further characterized as "H," "M," or "L" for High, Medium and Low.

SWMU #	Name	Soil	GW	sw	Air
1	Earthen Disposal Pit	PH	PM	PL	PL
2	Acid Collection/Neutralization Tank	PM	PM	PM	PL
3	Battery Storage Area	V	PM	PM	PL
4	Effluent Treatment Area	PL	PL	PM	PL
5	WW Treatmt Sludge Collection System		PM	PM	PM
6	Earthen Acid Dump Pit		D	PH	PM
7	Slag Storage Pile		PM	PM	PM
8	Crushed Battery Storage Area		PM	PM	PL
9	Hard Rubber Chip Storage Area	V	PM	PM	PL
10	Old Battery Separation Building	D	D	PH	PL
11	Old Mixed Metals Extrusion Bldg	PH	D	PH	PL
12	Zinc Alloy Operations Area	PH	D	PM	PL
13	Metal Warehouse	?	?	?	PL

SWMU#	Name	Soil	GW	sw	Air
14	Smelting Pots	D	PH	PH	PL
15	Lead Oxide Building & Warehouse	V	PH	PH	PL
16	Main Smelting Building	PH	PH	PH	PL
17	Blast Furnace Flue Bins	PH	PH	PH	PL
18	Main Smelting Building Baghouses	PM	PM	PH	PL
19	Crushed Battery Storage/Case Elevator	PH	PH	PH	PL
20	Radiation Lab/North Radiation Yard	PH	PM	PH	PL
21	Acid Tanks	PM	PM	PM	PL
22	Sumps	PM	PM	PM	PL
23	Mud and Dross Bins	PH	PM	PM	PL
24	Rainwater Retention Pond	V	РН	PH	PL
25	Truck Wash Pit	РН	PM	PM	PL
26	Truck Dumper	PM	PM	PM	PL
27	Battery Hopper/Oscillating Conveyor	PM	PM	PM	PL
28	Polypropylene Loading Dock	V	PH	PH	PL
29	Crushed Drum Storage Piles	V	PH	PH	PL
30	Battery Storage Areas	PH	PM	PM	PL
31	Reverbatory Furnace Feedback Room	PM	PM	PM	PL
32	Acid Tank and Battery Dump Bin Sump	PM	PM	PM	PL
33	Hammer Mill Conical Collector	PM	PM	PM	PL
34	Muds Holding Tanks	PM	PM	PM	PL
35	Baghouse Dust Slurry Sumps	PM	PM	PM	PL
36	Reverbatory and Soft Lead Baghouses	PM	PM	PM	PL
37	Blast Furnace Feedstock Room	PM	PM	PM	PL
38	Alloy Kettles & Casting Machinery	PM	PM	PM	PL
AOC 1	Two 10,000-Gal Fuel USTs	PM	PM	PM	PL

SWMU #	Name	Soil	GW	sw	Air
AOC 2	Solid Soda Ash Storage Tanks	PH	PM	PM	PL
AOC 3	Offsite Soils (added after RFA)	D	PL	PM	PM

IJ

A. Hazardous Waste Exposure and Constituent Information Instructions:
1. Designate as appropriate: D - documented evidence, V - visual evidence, P -potential for release. Specify documentation, who saw visual evidence, and/or rationale for potential release, if known.
2. Provide released or potentially released listed waste or constituent information to each appropriate media. Include volume of waste released, if known, toxicity, and physical state of contaminants.
3. Indicate whether release has already been remediated.
PM Imminent danger to public health/environment. Immediate action required; explain: DTSC Region 3 has documented the presence of lead contamination in offsite surface soils adjacent to the site. This surface soils contamination may pose an immediate hazard.
YE Stabilization measures appropriate; explain: Exposure controls or removal actions to prevent exposure to lead-contamininated offsite soils should be implemented Additional interim measures onsite to prevent/minimize spread of contamination could also be implemented.
D Release to soil. D V P Documented releases of lead above Region 9 PRG of 400 ppm at several SWMUs as indicated in SWMU table.
D Release to groundwater. D V P Documented release of lead, TCE, and other contaminants to GW at units indicated in SWMU table.
P Release to surface water. D V P No documented releases to SW, potential releases are indicated in SWMU table.
P Release to air. D V P No documented releases to air, potential

releases are indicated in SWMU table.

High Potential for Migration (media:)
Sensitive environmental receptors onsite or within 3 miles Explain:
No releases
Extent of Site Characterization (check one):
X_minimalextensiveunknown
B. Exposure Considerations: (D - Documented, P - Potential) Skip this section if there is no potential or documented release.
1. Groundwater (GW): If potential exposure is a concern, please specify whether release is "highly suspected" (HS). A highly suspected release to groundwater means that there is known soil contamination from a large volume of mobile constituents with high migration potential where there is no known aquiclude between contaminated soil and ground water.
Current GW drinking water source impacted
Sole Source (Class I) aquifer impacted
X Impacts on potable water aquifer but not currently used for drinking
Depth to GW_70' GW flow direction_WEST_
Direction/Distance to nearby wells 0.7 mi. WEST
Population Served <u>UNKNOWN</u>
2. Surface Water (SW): Los Angeles River
NO SW drinking water source impacted
Direction/Distance to SW0.1 mi. south
> 4 mi. Distance to sensitive environment related to SW contamination

> 4	mi. Distance to drinkin	ng water supply intake or contact point
Net I	Precipitation -10"	24 hour rainfall 3"
Perm	itted outfall yes	Permit Violations_yes
NO	Flood prone area	NO 100-yr flood plain
NO	Fishing, recreation w	vater source impacted
NO	Irrigation, livestock	water source impacted
initial staff prioriti with the recommen	izing process. The infindation.	Estuary factors should <u>not</u> be considered in the formation will be considered by management
Check if cor	itamination affects any	of the following near coastal waters:
	Apra Harbor (Guam) Babelthaup Island Bay Kaiaka Bay (Hawaii) Kailua Bay (Hawaii) Kona Coast (Hawaii) Morro Bay (California Pago Pago Harbor (An Pearl Harbor (Hawaii) San Diego Bay (Califo Tijuana Estuary (Califo	n) merican Samoa) ornia)
	ntamination affects either San Francisco Bay/Del Santa Monica Bay	er of these Estuary projects: Ita
3. <u>Air</u> :		
<u>PH</u>	Blowing dust; nearby	population
YES	Air permits YES	Permit violations

lead .

PH Can contaminants migrate into air? Airborne dust and soils containing

	<u>0.75 mi.</u> Target Pop <i>unknown</i> .	oulation < 4 miles	Nearest residential area, population
	4. <u>On site</u> :		
	Accessibility:	inaccessible limited access _ poor security	
	X Observed sur Access to offsite sur		ation nation is unrestricted.
III. SI	TE ENVIRONMENTAL F	PRIORITY	
		in terms of potent	al considerations only. Final priority ial exposure to human health and the tions in Sec. II.
<u>X</u>	High Priority		
	potential for, exposure to he near coastal waters and estu	uman population a nary project sites), vn or highly suspe	as resulted in, or which has high and sensitive environments (other than in the short term (< 10 years). Choose cted contamination to a sole source
	Medium Priority		
		•	ential for exposure to human health and all waters and estuary project sites) in the
	Low Priority		
	* Known or highly suspected the environment.	ed release, but unli	kely adverse effect on human health and

	No Further Action					
	* No evidence of a re environment.	lease that could adv	ersely affect human l	nealth and the		
<u>X</u>	NCAPS Priority	<u>High</u>	Medium	Low		
	* Check if NCAPS hapriority. If the NCAP discuss below.	_		ate NCAPS-based r assessment of priority,		
site. A	nents/Rationale to suppo Access to these areas is mination onsite may also	unrestricted, posing	a possible immediat	e hazard. Soil and GW		
IV. R	A. Contact Person(s):	STATUS				
#	Name	Contact Date	Phone	Agency		
1	Alan Sorsher	12/6/94	818/551-2892	DTSC-FPB		
	B. Current Status: Instructions: For source, indicate file document or numeral for contact person listed above.					
	X Operating RCRA TSDF; Source: RCRIS,1					
	Not Operating RCRA TSDF; Source:					
	Bankrupt Facility; Source:					
	Non-Notifying T submit a Part	SDF - should be a lead of A permit application		n't		
	Generator only - never operated as a TSDF Source:					

X Permitted TSDF or Seeking Permit; Source: RCRIS, 1
Part B Permit Application Submitted? Y N
Permit Application Review Lead (circle) EPA STATE OTHER (specify)
Corrective Action in (draft) Permit? Y N (Draft permit not yet prepared.)
Expected Permit Issuance Date: fall 1995
Closed or Closing Facility; Source:
Post-Closure permit; Source:
Combination: some units closing, some seeking permit (i.e. partial closure).
Part A Withdrawal Candidate; Source:
RWQCB WDRs requiring investigation and/or remediation in Effect

V. OTHER REGULATORY ACTIVITIES RELEVANT TO CORRECTIVE ACTION

A. Contact Person(s):

#	Name	Contact Date	Phone	Agency
10	Nancy Steele	12/6/94	818/551-2868	DTSC-SEB

B. Activity Instructions: mark all applicable; note any pertinent outstanding violations.
EPA Enforcement Action with Activities Relevant to Corrective Action; Source
X State Enforcement Activities Relevant to Corrective Action; Source: 1 Date: July 1994 Explain: Soil sampling conducted by SEB during the summer of 1994
confirmed the presence of lead contamination in offsite surface soils.
Regional Water Board Order or WDR Requiring Corrective Action; Source:

VI. C		E LEVEL OF INV state actions, leve			LEAN-UP ACTIVITIES 's oversight)
	Mark one:	Medium		-	- ,
	Iligii	Wedium	Low		_ None
yet be	Rationale: There een initiated.	e have been no clea	anup activities	to date	e. Corrective action has not
VII.	FACILITY WILL	INGNESS/ABILI	TY TO PERF	ORM	CORRECTIVE ACTION
	Facility is	cooperative			
	Facility is	uncooperative; Ex	plain:		
	X Unknown				
	Facility ma	y be financially ur	nable to comple	te woi	rk.
VIII.		sider factors in Sec	ctions I - VII to	arriv	ark all applicable) e at final recommendation for ritize as Action 1, 2, etc.
		and substantial dang of RCRA 7003 Or			or the environment requires 106 Order.
	X Stabilization	on evaluation comp	pleted		
,	Sta Sta	bilization required bilization not requ bilization not feasi ther investigation	ired ble		
		A 3013 order. Rele health or the envir			ste presents a substantial n only).
	Refer to CI	ERCLA for further	follow-up.		
	X No further	CERCLA action			

Conduct an KFA
Use a 3007 letter to obtain more information regarding the following items:
Negotiate 3008(h) Consent Order
Incorporate corrective action into post-closure permit through 3004(u) and (v).
Incorporate corrective action into permit through 3004(u) and (v). Allen Sorsher, Unit Chief in DTSC Region 3 permitting branch, has agreed to include corrective action in the permit scheduled to be issued by the fall of 1995.
Include corrective action in closure plan (surface releases near regulated units)
Ongoing or planned State action is sufficient to address release(s).
No further RCRA action at present; re-evaluate next year.
No further RCRA action.
Recommendation Accepted
Larry Bowerman, Chief Corrective Action Section
concense reading section
Environmental Benefits:
Raise priority to due to near coastal waters impacts.
Raise priority to due to estuary project impacts.